

Uzupełnienie 911 008 60

Product Code: 911 008 70

Availability: In Stock

Description

[Vibration Damper Holding Tool - 1.8/2.0 TFSi/TSi VAG](#)

A tool for disassembly and assembly of the crankshaft vibration damper VW / AUDI / SKODA / SEAT (petrol) 1.8 / 2.0 TFSI / TSI

(for generation engines: 3 EA888 after 2007) factory tool number: **OEM T10531**

Engines:

1.8: BZB, CDAA, BPU, BYT, CABA, CABB, CDHA, CDHB, CABD, DAJB, CJSA, CJSB, CJEB, CJEE, CJED, CYGA, CDAC, CJSC, CGYA, DAJA, DAJB

2.0: CAWB, CCZA, CBFA, CCTA, CDNB, CDNC, CDND, CJXA, CJXE, CJXH, CHHB, CHHA, CULA, CFKA, DEDA, CHJA, CAWA, CCZC, CCZD, CPSA, CJK, CJKB, CESA, CETA, CFPA, CNCD, CPLA, CYRB, CYRC, CNCE, CYNB, CYP, CULB, CULC, CNCB, CWZA, CJXF, CJXC, CJXB, CJXG, CHHC, CCZB, CPZA, CESA, CNCD, CYPB

OEM Number

OEM: T10531